ಬೃಹತ್ ಬೆಂಗಳೂರು ಮಹಾನಗರ ಪಾಲಿಕೆ
Bruhat Bangalore Mahanagara Palike

BBMP ENGINEERING DEPARTMENT

Road History Data Sheet

General

Zone	Ward No.	Ward Name
YELAHANKA	1	Kempegowda Ward
Street ID	**Street Name**	**Significant Landmark**
W0267	Maheshwari Nagar Ambedkar Rd	kandappa graden
Segment No.	**Total Length (m)**	
1/S-W0267/S111705	373.19	

Segment Details

Seg No.	Length (m)	Start Coordinates		End Coordinates		From	To
1	373.19	77.607110	13.104468	77.607506	13.101117	RI-A07	DEAD END

Work Details

History of Road / Lane / Circles

Name of the Work	Sanctioned Estimated Amount (Rs.)	Sanctioned Year
Construction of Drain at kandappa graden in ward no 01 Yelahanka Sub-Division Yelahanka zone	1600000	2015
Year	**Type of Work**	**Other Work Type**
2015 - 2016	Asphalting	
Tender	**Work Details**	**Job No. / Work Code**
Tender	Construction of Drain at kandappa graden in ward no 01 Yelahanka Sub-Division Yelahanka zone	001-16-000011
Work Order No.	**Work Order Date**	**Period of Extention**
EE(YNK.D)/E-PMT-1/WO/27/2015-16	24/02/2016	90 DAYS
Defect Liability Period From	**Defect Liability Period To**	**Multiple road involved with the same Job No/ Work Code #**
24/02/2016	23/02/2017	Yes

Contractor Details

Name of Contractor	Contractor Reg No (BBMP/PWD)	Expenditure Booked \ Released (Rs)
SRINIVAS B M		0.00
Phone No.	**E-Mail ID**	
9845122827		

Field Inspection Details

Zone: YELAHANKA Ward No: 1 Ward Name: Kempegowda Ward Street ID: W0267

Date: 03/12/2016 Time: 13:39:26 RH20161203133926

Number of Trees	Any Other Information	Name
1		CHANDRASHEKAR
Date of Inspection	**Remarks**	
03/12/2016	COMPLETED	

Category	Image	Photo Remark
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.
Drain Condition		This photo seems out of range.

Remarks

Designation	Approver Name	Date	Target Date	Remark
CE	PARAMESHWARAIAH	03/12/2016	02/01/2017	COMPLETED
SE	VASU K M	03/12/2016	02/01/2017	COMPLETED
EE	VASU K M	03/12/2016	02/01/2017	COMPLETED
AEE	G.B. PRABHAKAR	03/12/2016	02/01/2017	COMPLETED
AE	CHANDRASHEKAR	03/12/2016	02/01/2017	COMPLETED
AE	CHANDRASHEKAR	03/12/2016	02/01/2017	COMPLETED